


# FY18 PAVEMENT IMPROVEMENTS, REPAIRS, AND MAINTENANCE


Base Bid

# NORTHWEST ENTRANCE TO LOT N5




Poor visibility to the West for vehicles leaving the lot & similarly for vehicles entering from the West.






As a result of the entrance, this row of the parking lot becomes a road, making it hazardous for vehicles parked on either side to pull out. This also give drivers a reason to drive across the lot at an angle which can result in unsafe traffic interactions.

NORTHWEST ENTRANCE TO LOT N5




## NORTHWEST ENTRANCE TO LOT N5

Instead of driving through  
the lot traffic will be forced  
onto the campus roads.



The only route for pedestrians to take from N5 to the OPS building is to walk through the middle of the intersection.

CROSSWALK TO OPS BUILDING



## CROSSWALK TO OPS BUILDING

Adding the sidewalk and crosswalks will improve safety by moving the pedestrian traffic out of the intersection and will emphasize the need to watch for pedestrians to drivers.




Walking path from  
HCC to DKN



FAILING SHOULDERS ON WAUBONSEE DRIVE





Asphalt pothole repairs at South Entrance  
(Waubonsee Drive)



Resurface from  
the sidewalk



to here

# LOT S5 (OVERFLOW LOT) WALKING PATH ASPHALT REPAIRS



Asphalt repairs at Southeast end of Circle Drive



Lot N8, adjacent drives, and AKL lot – crack-filling, seal-coating & re-stripping



Lot N8, adjacent drives, and AKL lot –  
crack-filling, seal-coating & re-striping

# Lot S1 – crack-filling, seal-coating & re-stripping





CONCRETE CURB REPLACEMENTS (LOT N8)



# CONCRETE CURB REPLACEMENTS (LOT N4)





# CONCRETE CURB REPLACEMENTS (CIRCLE DR & LOT S1)



ADD SPILLWAY AT CURB AT SW CORNER  
OF WAUBONSEE DRIVE & CIRCLE DRIVE



Concrete pothole repair at South entrance  
(Waubonsee Drive)



EAST ENTRANCE TO APC BUILDING - REMOVE AND REPLACE SIDEWALK INCLUDING ADA RAMP

# REPLACE DAMAGED OR SETTLED SIDEWALK

South of AUD



Southwest of COL @ Circle





Demolish circle & walks & replace with standard blonde concrete walk

REPLACE DECORATIVE PERMEABLE PAVER CIRCLE OFF SOUTHWEST CORNER OF SCI BUILDING

Decorative paver circle West of SCI




Decorative paver circle North of COL



REPLACE DAMAGED CURBS AT  
DECORATIVE PAVER CIRCLES

Large decorative paver circle  
between SCI, ERK, COL, & AUD




Decorative paver circle East of SCI  
(Near ERK)



REPLACE DAMAGED CURBS AT  
DECORATIVE PAVER CIRCLES




# DECORATIVE INLAYED PAVERS (IN CONCRETE)



Decorative inlaid pavers North of APC building



Decorative inlaid pavers West of APC building



Decorative inlaid pavers Southeast of APC building

Note: See slide 21 for a picture of the decorative circle at the Southwest corner of COL

# DECORATIVE INLAVED PAVERS (IN CONCRETE)

## Decorative paver half circle North of SCI



Note: For other decorative paver areas:

- Circle West of SCI – See slide 23
- Circle East of SCI (near ERK) – See slide 24
- Large circle between COL, SCI, ERK, & COL – See slide 24
- Circle at North entrance to COL – See slide 23

# DECORATIVE PERMEABLE PAVER CIRCLES




Re-set settled pavers in noted areas to eliminate trip hazards




Replace damaged pavers in noted areas. (WCC has stockpile of pavers to be used for this)

# SETTLED & DAMAGED PAVERS IN LOT N1



# AURORA DOWNTOWN CAMPUS SETTLED PAVER REPAIRS



# AURORA DOWNTOWN CAMPUS SETTLED PAVER REPAIRS



South Entrance



Inlaid bricks next to South Entrance

# AURORA DOWNTOWN CAMPUS SETTLED PAVER REPAIRS

# FY18 PAVEMENT IMPROVEMENTS, REPAIRS, AND MAINTENANCE

Bid  
Alternates


A decorative graphic consisting of several parallel white lines of varying thicknesses, slanted diagonally from the bottom-left towards the top-right, set against a solid blue background.





Saw cut & re-pour concrete to raise up transition to eliminate lip

# OPS BUILDING LOADING DOCK




North Entrance




South Entrance

# PLANO CAMPUS SETTLED PAVER REPAIRS

# PLANO CAMPUS SETTLED PAVER REPAIRS



Settlement at concrete delivery area transition



Settlement at corner of lot near delivery area



Settlement near far Northeast corner

# PLANO CAMPUS SETTLED PAVER REPAIRS